



**DAEWOO MOTOR AMERICA, INC.**

1065 W. Victoria St., Compton, CA 90220 / Tel: (310) 223-5900 / Fax: (310) 669-2000

January 18, 2000

Jonathan D. White, Chief  
Office of Defects Investigation  
U.S. Department of Transportation  
National Highway Traffic Safety Administration  
400 Seventh St., S.W.  
Washington, D.C. 20590

Re: Lanos Alloy Wheel Bolt Torque – 99V-336

Dear Mr. White:

In accordance with Title 49 of the Code of Federal Regulations, Part 573.6, fourth quarter report information for the above referenced Safety Recall is attached.

If you should require any further information, do not hesitate to contact me at (909) 390-1100 ext. 213, fax (909) 390-9056.

Respectfully,

  
Kwang Sup Hwang  
Manager, North American Certification

## Safety Recall Quarterly Report Information

Required per 49 CFR Part 573.6

Report Date: 1/18/2000 Calendar Quarter: 4<sup>th</sup> Quarter, 1<sup>st</sup> Report  
Safety Recall Quarterly Report through: 12/31/99  
Manufacturer: Daewoo Motor Co. LTD.  
Report Author: K. S. Hwang Phone: (909) 390-1100 ext. 213  
Recall Subject: Lanos Alloy Wheel Bolt Torque

1. NHTSA Safety Recall Campaign Number: 99V-336

Also, for completeness, if your company has assigned a code number to this campaign, please provide your code: T99-2-02

2. (a) The date notification to purchasers began: 12/03/99

(b) The date notification of purchasers was completed: 12/03/99

3. The Total Number of Items Involved: 2811

The total number of items involved in the subject campaign (including all items sold or distributed to purchasers, dealers, distributors, and similar entities beyond the immediate control of the manufacturer/importer).

Number of Items Returned from Inventory or Remedied Prior to Sale: 461

Includes (a) the total number of items returned from Manufacturer, Distributor, Dealer or Retailer inventory or (b) otherwise remedied prior to sale to consumers.

4. (a) Total Number Inspected & Remedied: 550

Total number of items, which were inspected and/ or otherwise repaired or remedied.

(b) Total Number Inspected & NOT REQUIRING REMEDY: N/A

5. Items Determined to be Unreachable

Total Number Exported: 0

Total Number Stolen: 0

Total Number Scrapped: (2) KLATC2265WB230607/ KLATC5261XB254180

Total Number Unable to Notify: 0

Total Number Otherwise Unreachable: 0

Describe Other: \_\_\_\_\_

**Safety Recall Quarterly Report Information**  
Required per 49 CFR Part 573.6

Report Date: 4/18/2000 Calendar Quarter: 1<sup>st</sup> Quarter, 2<sup>nd</sup> Report  
Safety Recall Quarterly Report through: 3/31/2000  
Manufacturer: Daewoo Motor Co. LTD.  
Report Author: K. S. Hwang Phone: (800) 946-0484  
Recall Subject: Lance Alloy Wheel Bolt Torque

1. NHTSA Safety Recall Campaign Number: 99V-336

Also, for completeness, if your company has assigned a code number to this campaign, please provide your code: T99-2-02

2. (a) The date notification to purchasers began: 12/03/99

(b) The date notification of purchasers was completed: 12/03/99

3. The Total Number of Items Involved: 2811  
The total number of items involved in the subject campaign (including all items sold or distributed to purchasers, dealers, distributors, and similar entities beyond the immediate control of the manufacturer/importer).

Number of Items Returned from Inventory or Remedied Prior to Sale: 461  
Includes (a) the total number of items returned from Manufacturer, Distributor, Dealer or Retailer inventory or (b) otherwise remedied prior to sale to consumers.

4. (a) Total Number Inspected & Remedied: 1111  
Total number of items, which were inspected and/ or otherwise repaired or remedied.

(b) Total Number Inspected & NOT REQUIRING REMEDY: N/A

5. Items Determined to be Unreachable

Total Number Exported: 0

Total Number Stolen: 0

Total Number Scrapped: (2) KLATC2285WB230607/ KLATC6261XB254180

Total Number Unable to Notify: 0

Total Number Otherwise Unreachable: 0

Describe Other: \_\_\_\_\_



**DAEWOO MOTOR AMERICA, INC.**

1055 W. Victoria St., Compton, CA 90220 / Tel: (310) 223-6900 Fax: (310) 669-2000

**July 18, 2000**

**Jonathan D. White, Chief  
Office of Defects Investigation  
U.S. Department of Transportation  
National Highway Traffic Safety Administration  
400 Seventh St., S.W.  
Washington, D.C. 20590**

**Re: Lanos Alloy Wheel Bolt Torque – 99V-336**

**Dear Mr. White;**

**In accordance with Title 49 of the Code of Federal Regulations, Part 573.6,  
second quarter report information for the above referenced Safety Recall is  
attached.**

**If you should require any further information, do not hesitate to contact me at  
(909) 946-0491, fax (909) 946-0494**

**Respectfully,**

  
**Kwang Sup Hyang  
Manager, North American Certification**

## Safety Recall Quarterly Report Information

Required per 49 CFR Part 573.6

Report Date: 7/18/2000 Calendar Quarter: 2nd Quarter, 3rd Report  
Safety Recall Quarterly Report through: 6/30/2000  
Manufacturer: Daewoo Motor Co. LTD.  
Report Author: K. S. Hwang Phone: (909) 946-0491  
Recall Subject: Lanos Alloy Wheel Bolt Torque

1. NHTSA Safety Recall Campaign Number: 99V-336

Also, for completeness, if your company has assigned a code number to this campaign, please provide your code: T89-2-02

2. (a) The date notification to purchasers began: 12/03/99

(b) The date notification of purchasers was completed: 12/03/99

3. The Total Number of Items Involved: 2811

The total number of items involved in the subject campaign (including all items sold or distributed to purchasers, dealers, distributors, and similar entities beyond the immediate control of the manufacturer/importer).

Number of Items Returned from Inventory or Remedied Prior to Sale: 461

Includes (a) the total number of items returned from Manufacturer, Distributor, Dealer or Retailer inventory or (b) otherwise remedied prior to sale to consumers.

4. (a) Total Number Inspected & Remedied: 1406

Total number of items, which were inspected and/ or otherwise repaired or remedied.

(b) Total Number Inspected & NOT REQUIRING REMEDY: N/A

5. Items Determined to be Unreachable

Total Number Exported: 0

Total Number Stolen: 0

Total Number Scrapped: (2) KLATC2265WB230607/ KLATC6261XB254100

Total Number Unable to Notify: 0

Total Number Otherwise Unreachable: 0

Describe Other: \_\_\_\_\_



**DAEWOO MOTOR AMERICA, INC.**

1055 W. Victoria St., Compton, CA 90220 / Tel: (310) 223-6900 Fax: (310) 669-2000

**October 18, 2000**

**Jonathan D. White, Chief  
Office of Defects Investigation  
U.S. Department of Transportation  
National Highway Traffic Safety Administration  
400 Seventh St., S.W.  
Washington, D.C. 20590**

**Re: Lanos Alloy Wheel Bolt Torque – 99V-336**

**Dear Mr. White;**

**In accordance with Title 49 of the Code of Federal Regulations, Part 573.6, third quarter report information for the above referenced Safety Recall is attached.**

**If you should require any further information, do not hesitate to contact me at (909) 446-1802.**

**Respectfully,**

  
**Kwang Sup Hwang  
Manager, North American Certification**

## Safety Recall Quarterly Report Information

Required per 49 CFR Part 573.6

Report Date: 10/18/2000 Calendar Quarter: 3<sup>rd</sup> Quarter, 4<sup>th</sup> Report  
Safety Recall Quarterly Report through: 9/30/2000  
Manufacturer: Daewoo Motor Co. LTD.  
Report Author: K. S. Hwang Phone: (909) 946-0491  
Recall Subject: Lanos Alloy Wheel Bolt Torque

1. NHTSA Safety Recall Campaign Number: 99V-336

Also, for completeness, if your company has assigned a code number to this campaign, please provide your code: T99-2-02

2. (a) The date notification to purchasers began: 12/03/99

(b) The date notification of purchasers was completed: 12/03/99

3. The Total Number of Items Involved: 2811  
The total number of items involved in the subject campaign (including all items sold or distributed to purchasers, dealers, distributors, and similar entities beyond the immediate control of the manufacturer/importer).

Number of Items Returned from Inventory or Remedied Prior to Sale: 461  
Includes (a) the total number of items returned from Manufacturer, Distributor, Dealer or Retailer inventory or (b) otherwise remedied prior to sale to consumers.

4. (a) Total Number Inspected & Remedied: 1441  
Total number of items, which were inspected and/ or otherwise repaired or remedied.

(b) Total Number Inspected & NOT REQUIRING REMEDY: N/A

5. Items Determined to be Unreachable

Total Number Exported: 0

Total Number Stolen: 0

Total Number Scrapped: (2) KLATC2265WB230607/ KLATC5261XB254160

Total Number Unable to Notify: 0

Total Number Otherwise Unreachable: 0

Describe Other: \_\_\_\_\_



RECEIVED

DAEWOO MOTOR AMERICA, INC.

1055 W. Victoria St., Compton, CA 90220 / Tel: (310) 223-5900 Fax: (310) 668-2008

01 JAN 31 AM 11:16

DEFECTS INVESTIGATION

January 18, 2001

Jonathan D. White, Chief  
Office of Defects Investigation  
U.S. Department of Transportation  
National Highway Traffic Safety Administration  
400 Seventh St., S.W.  
Washington, D.C. 20590

Re: Lanos Alloy Wheel Bolt Torque – 99V-336

Dear Mr. White;

In accordance with Title 49 of the Code of Federal Regulations, Part 573.8, fourth quarter report information for the above referenced Safety Recall is attached.

If you should require any further information, do not hesitate to contact me at (909) 466-1602.

Respectfully,

Kwang Sup Hwang  
Manager, North American Certification



## Safety Recall Quarterly Report Information

Required per 49 CFR Part 573.6

Report Date: 1/18/2001 Calendar Quarter: 4<sup>th</sup> Quarter, 5<sup>th</sup> Report

Safety Recall Quarterly Report through: 12/30/2000

Manufacturer: Daewoo Motor Co. LTD.

Report Author: K. S. Hwang Phone: (909) 466-1602

Recall Subject: Lance Alloy Wheel Bolt Torque

1. NHTSA Safety Recall Campaign Number: 99V-336

Also, for completeness, if your company has assigned a code number to this campaign, please provide your code: T99-2-02

2. (a) The date notification to purchasers began: 12/03/99

(b) The date notification of purchasers was completed: 12/03/99

3. The Total Number of Items Involved: 2811

The total number of items involved in the subject campaign (including all items sold or distributed to purchasers, dealers, distributors, and similar entities beyond the immediate control of the manufacturer/importer).

Number of Items Returned from Inventory or Remedied Prior to Sale: 461

Includes (a) the total number of items returned from Manufacturer, Distributor, Dealer or Retailer inventory or (b) otherwise remedied prior to sale to consumers.

4. (a) Total Number Inspected & Remedied: 1487

Total number of items, which were inspected and/ or otherwise repaired or remedied.

(b) Total Number Inspected & NOT REQUIRING REMEDY: N/A

5. Items Determined to be Unreachable

Total Number Exported: 0

Total Number Stolen: 0

Total Number Scrapped: (2) KLATC2265WB230607/ KLATC5261XB254180

Total Number Unable to Notify: 0

Total Number Otherwise Unreachable: 0

Describe Other: \_\_\_\_\_



**DAEWOO MOTOR AMERICA, INC.**

1055 W. Victoria St., Compton, CA 90220 / Tel: (310) 223-5900 Fax: (310) 669-2000

**April 18, 2001**

**Jonathan D. White, Chief  
Office of Defects Investigation  
U.S. Department of Transportation  
National Highway Traffic Safety Administration  
400 Seventh St., S.W.  
Washington, D.C. 20590**

**Re: Lanos Alloy Wheel Bolt Torque – 99V-336**

**Dear Mr. White;**

**In accordance with Title 49 of the Code of Federal Regulations, Part 573.6, first quarter, sixth and final report information for the above referenced Safety Recall is attached.**

**If you should require any further information, do not hesitate to contact me at (310) 884-3322**

**Respectfully,**

A handwritten signature in black ink, appearing to read 'Walter E. Schwarz', written over a horizontal line.

**Walter E. Schwarz  
Manager, Product Support**

RECEIVED  
OFFICE OF DEFECTS INVESTIGATION  
U.S. DEPARTMENT OF TRANSPORTATION  
APR 20 2001 PM 1:00

## Safety Recall Quarterly Report Information

Required per 49 CFR Part 573.6

Report Date: 4/18/2001 Calendar Quarter: 1<sup>st</sup> Quarter, 6<sup>th</sup> Report  
Safety Recall Quarterly Report through: 3/31/2001  
Manufacturer: Daewoo Motor Co., LTD.  
Report Author: W. E. Schwarz Phone: (301) 884-3322  
Recall Subject: Lanos Alloy Wheel Bolt Torque

1. NHTSA Safety Recall Campaign Number: 99V-336

Also, for completeness, if your company has assigned a code number to this campaign, please provide your code: T99-2-02

2. (a) The date notification to purchasers began: 12/03/99

(b) The date notification of purchasers was completed: 12/03/99

3. The Total Number of Items Involved: 2811  
The total number of items involved in the subject campaign (including all items sold or distributed to purchasers, dealers, distributors, and similar entities beyond the immediate control of the manufacturer/importer).

Number of Items Returned from Inventory or Remedied Prior to Sale: 461  
Includes (a) the total number of items returned from Manufacturer, Distributor, Dealer or Retailer inventory or (b) otherwise remedied prior to sale to consumers.

4. (a) Total Number Inspected & Remedied: 1513  
Total number of items, which were inspected and/ or otherwise repaired or remedied.

(b) Total Number Inspected & NOT REQUIRING REMEDY: N/A

5. Items Determined to be Unreachable

Total Number Exported: 0

Total Number Stolen: 0

Total Number Scrapped: (2) KLATC2265WB230607/ KLATC5261XB254180

Total Number Unable to Notify: 0

Total Number Otherwise Unreachable: 0

Describe Other: \_\_\_\_\_

## Safety Recall Quarterly Report Information

Required per 49 CFR Part 573.6

Report Date: 01/28/2000 Calendar Quarter: 4th. Quarter-1999

Safety Recall report through: 12/31/1999

Manufacturer: Daewoo Motor Co., LTD.

Report Author: K.S. Hwang Phone: (909) 846-0491

Recall Subject: Alloy Wheel Bolt Torque

1. NHTSA Safety recall Campaign Number 98V-336.002

Also, for completeness, if your company has assigned a code number to this campaign, please provide your code: RSB-002-89

2. (a) The date notification to purchaser began: 12/09/1999

(b) The date notification of purchasers was completed: 12/14/1999

3. The Total Number of Items Involved: 1,634

The total number of items involved in the subject campaign (including all items sold or distributed to purchasers, dealers, distributors, and similar entities beyond the immediate control of the manufacturer/importer.)

Number of Items Returned from Inventory or Remedied Prior to Sale: 38

Include (a) the total number of items returned from Manufacturer, Distributor, Dealer or Retailer Inventory or (b) otherwise remedied prior to sale to customers.

4. (a) Total Number Inspected and Remedied: 405

Total number of items, which were inspected and/or otherwise repaired and remedied.

(b) Total Number Inspected & NOT REQUIRING REMEDY: N/A

### 5. Items Determined to be Unreachable

Total Number Exported: 0

Total Number Stolen: 23 (List Enclosed)

Total Number Scrapped: 17 (List Enclosed)

Total Number Unable to Notify: 191 (List Enclosed)

Total Number Otherwise Unreachable: 4 (List Enclosed)

Describe Other: Repossessed by Banks

## Safety Recall Quarterly Report Information

Required per 49 CFR Part 573.6

Report Date: 04/10/2000 Calendar Quarter: 1st. Quarter

Safety Recall report through: 03/30/2000

Manufacturer: Daewoo Motor Co., LTD.

Report Author: K.S. Hwang Phone: (800) 946-0491

Recall Subject: Alloy Wheel Bolt Torque

**1. NHTSA Safety recall Campaign Number**

23/  
98V-000,002

Also, for completeness, if your company has assigned a code number to this campaign, please provide your code: RSB-002-00

**2. (a) The date notification to purchaser began:**

12/08/1999

**(b) The date notification of purchasers was completed:**

12/14/1999

**3. The Total Number of Items Involved:**

1,634

The total number of items involved in the subject campaign (including all items sold or distributed to purchasers, dealers, distributors, and similar entities beyond the immediate control of the manufacturer/importer.)

Number of Items Returned from Inventory or Remedied Prior to Sale:

38

Include (a) the total number of items returned from Manufacturer, Distributor, Dealer or Retailer Inventory or (b) otherwise remedied prior to sale to customers.

**4. (a) Total Number Inspected and Remedied:**

645

Total number of items, which were inspected and/or otherwise repaired and remedied.

**(b) Total Number Inspected & NOT REQUIRING REMEDY:**

N/A

**5. Items Determined to be Unreachable**

Total Number Exported:

0

Total Number Stolen:

22

(List Enclosed)

Total Number Scrapped:

18

(List Enclosed)

Total Number Unable to Notify:

137

Total Number Otherwise Unreachable:

35

(List Enclosed)

Describe Other: Repossessed by Banks: 35

## Safety Recall Quarterly Report Information

Required per 49 CFR Part 573.8

Report Date: 06/30/2000 Calendar Quarter: 2nd. Quarter

Safety Recall report through: 08/30/2000

Manufacturer: Daewoo Motor Co., LTD.

Report Author: K.S. Hwang Phone: (909) 946-0491

Recall Subject: Alloy Wheel Bolt Torque

### 1. NHTSA Safety recall Campaign Number

99V-136-002  
~~99V-000-001~~

Also, for completeness, if your company has assigned a code number to this campaign, please provide your code: RSE-002-99

2. (a) The date notification to purchaser began: 12/09/1999

(b) The date notification of purchasers was completed: 12/14/1999

3. The Total Number of Items Involved: 1,834

The total number of items involved in the subject campaign (including all items sold or distributed to purchasers dealers, distributors, and similar entities beyond the immediate control of the manufacturer/importer.)

Number of items Returned from Inventory or Remedied Prior to Sale: 38

Include (a) the total number of items returned from Manufacturer, Distributor, Dealer or Retailer Inventory or (b) otherwise remedied prior to sale to customers.

4. (a) Total Number Inspected and Remedied: 734

Total number of items, which were inspected and/or otherwise repaired and remedied.

(b) Total Number Inspected & NOT REQUIRING REMEDY: N/A

### 5. Items Determined to be Unreachable

Total Number Exported: 0

Total Number Stolen: 19 (List Enclosed)

Total Number Scrapped: 18 (List Enclosed)

Total Number Unable to Notify: 137

Total Number Otherwise Unreachable: 28 (List Enclosed)

Describe Other: Repossessed by Banks 33



DAEWOO MOTOR AMERICA, INC.

1055 W. Victoria St., Compton, CA 90220 / Tel: (310) 223-5900 Fax: (310) 669-2000

January 30, 2001

Jonathan D. White, Chief  
Office of Defects Investigation  
U.S. Department of Transportation  
National Highway Traffic Safety Administration  
400 Seventh St., S.W.  
Washington, D.C. 20590

Re: Allow Wheel Bolt Torque # 99V-336.002

Dear Mr. White;

In accordance with Title 49 of the Code of Federal Regulations, Part 573.6, fourth quarter report information for the above referenced Safety Recall for Daewoo Motor de Puerto Rico, Inc. is attached.

If you should require any further information, do not hesitate to contact me at (909) 488-1602.

Respectfully,

  
Kwang Sup Hwang  
Manager, North American Certification

01 JAN 31 PM 2:05  
DEFECTS INVESTIGATION  
OFFICE OF DEFECTS INVESTIGATION

## Safety Recall Quarterly Report Information

Required per 49 CFR Part 573.6

Report Date: 01/30/2001 Calendar Quarter: 4th. Quarter

Safety Recall report through: 12/30/2000

Manufacturer: Daewoo Motor Co., LTD.

Report Author: Boung-youn Kim Phone: (787) 784-2777 ext. 228

Recall Subject: Alloy Wheel Bolt Torque

1. NHTSA Safety recall Campaign Number 99V-336.002

Also, for completeness, if your company has assigned a code number to this campaign, please provide your code: RSB-002-99

2. (a) The date notification to purchaser began: 12/09/1999

(b) The date notification of purchasers was completed: 12/14/1999

3. The Total Number of Items Involved: 1,634

The total number of items involved in the subject campaign (including all items sold or distributed to purchasers, dealers, distributors, and similar entities beyond the immediate control of the manufacturer/importer.)

Number of Items Returned from Inventory or Remedied Prior to Sale: 38

Include (a) the total number of items returned from Manufacturer, Distributor, Dealer or Retailer Inventory or (b) otherwise remedied prior to sale to customers.

4. (a) Total Number Inspected and Remedied: 791

Total number of items, which were inspected and/or otherwise repaired and remedied.

(b) Total Number Inspected & NOT REQUIRING REMEDY: N/A

### 5. Items Determined to be Unreachable

Total Number Exported: 0

Total Number Stolen: 19

Total Number Scrapped: 18

Total Number Unable to Notify: 137

Total Number Otherwise Unreachable: 24

Describe Other: Repossessed by Bank 24





DAEWOO MOTOR AMERICA, INC.

1055 W. Victoria St., Compton, CA 90220 / Tel: (310) 223-5900 Fax: (310) 669-2000

April 18, 2001

Jonathan D. White, Chief  
Office of Defects Investigation  
U.S. Department of Transportation  
National Highway Traffic Safety Administration  
400 Seventh St., S.W.  
Washington, D.C. 20590

Re: Lanos Alloy Wheel Bolt Torque #99V-000-001 <sup>336.002</sup>

Dear Mr. White;

In accordance with Title 49 of the Code of Federal Regulations, Part 573.6, first quarter, sixth and final report information for the above referenced Safety Recall for Daewoo Motor de Puerto Rico, Inc. is attached.

If you should require any further information, do not hesitate to contact me at (310) 884-3322

Respectfully,

  
Walter E. Schwarz  
Manager, Product Support

RECEIVED  
OFFICE OF DEFECTS INVESTIGATION  
APR 20 PM 1:03

## Safety Recall Quarterly Report Information

Required per 49 CFR Part 573.6

Report Date: 4/18/2001 Calendar Quarter: 1st Quarter, 2001 6th Report

Safety Recall Quarterly Report through: 3/31/2001

Manufacturer: Daewoo Motor Co. LTD.

Report Author: W.E.Schwarz Phone: (310) 884-3322

Recall Subject: Lanos Alloy Wheel Bolt Torque

1. NHTSA Safety Recall Campaign Number: 99V-090.001

Also, for completeness, if your company has assigned a code number to this campaign, please provide your code: RSB-002-99

2. (a) The date notification to purchasers began: 12/09/1999

(b) The date notification of purchasers was completed: 12/14/1999

3. The Total Number of Items Involved: 1,634

The total number of items involved in the subject campaign (including all items sold or distributed to purchasers, dealers, distributors, and similar entities beyond the immediate control of the manufacturer/importer).

Number of Items Returned from Inventory or Remedied Prior to Sale: 38

Includes (a) the total number of items returned from Manufacturer, Distributor, Dealer or Retailer inventory or (b) otherwise remedied prior to sale to consumers.

4. (a) Total Number Inspected & Remedied: 809

Total number of items, which were inspected and/ or otherwise repaired or remedied.

(b) Total Number Inspected & NOT REQUIRING REMEDY: 0

5. Items Determined to be Unreachable

Total Number Exported: 0

Total Number Stolen: 8

Total Number Scrapped: 5

Total Number Unable to Notify: 137

Total Number Otherwise Unreachable: 34

Describe Other: Repossessed by the bank